

Accident

On the morning of June 12, 2024, a staff member placed the 15L dewer liquid nitrogen tank on the tank cart and planned to fill liquid nitrogen. When he arrived at the lab, he found that another person was filling the tank, then he left the 15L tank behind and went out of the room for other matters.

About 2 minutes later, he returned to the lab, he found that the other person had connected the liquid nitrogen discharge pipe to his 15L liquid nitrogen tank (the tank was still on the cart) and that the person had left the scene. He decided from past experience that it would take some time to fill up, so he left the lab again to attend to other matters.

About 2 minutes later, when he returned to the lab again, he found that the liquid nitrogen had overflowed to the lab floor. He closed the discharge valve immediately and reported the case. It caused a small range of PVC floor rupture, no injuries. This case was identified as Near Miss.



**SAFETY
ALERT**

GROUND DAMAGE INCIDENTS CAUSED BY LIQUID NITROGEN OVERFLOW

Reason

No procedure indicates that the whole process of liquid nitrogen filling task should be under monitoring and the filling task should be carried out in a secondary container (leakage tray)

There is no training record for all personnel who would perform the liquid nitrogen filling task.

Lack of communication for the handover and inadequate on-site monitoring during liquid nitrogen filling.

PVC floor is not protected against liquid nitrogen leakage.

Experience

Update SOP

Organizing local training

Make Sure any handover task have a good communication and monitor the whole process of filling.

Add carpet to liquid nitrogen handling area to protect PVC floor.

